

2026 Holy Cross Church Building Quinquennial Review

SUMMARY OF JOBS

| | <i>Urgency</i> | <i>Progress</i> |
|---|-----------------------|----------------------------------|
| E01 external lighting | | |
| E02 Notice Board | | |
| E03 Fire safety | | |
| L01 Lobby – sealing joint | | |
| L02 Lobby emergency lighting | | |
| L03 Lobby Stairs | | |
| C01 Church walls | | |
| C02 Church Sacristy | | |
| C03 Plant room | | |
| C04 Church building: heating | | |
| C05 Fire safety | | |
| U01 Upper Room flooring | | |
| U02 Upper Floor toilets | | |
| U03 Chair lift to upper room | | Being explored |
| E1 External - Front & side elevation window frame | | |
| E2 External – entrance doors | | |
| E3 Roof | | |
| E4 External – rear elevation | | |
| E5 External: - side elevation to steps | | |
| COMPLETED | | |
| E04 Asbestos remediation | | Completed by contractor Dec 2025 |
| E6 External – side elevation flat roof | | |
| E7 External – side elevation to house | | |
| E8 External - side elevation escape stairs | | |
| E9 External - side elevation overhead cable | | |

2026 Holy Cross Church Building Quinquennial Review

| | |
|------------------------------|--|
| <i>Location: Entrance</i> | |
| E01 External lighting | |
| <i>Description:</i> | Link outside light to main lighting circuits via fused spur. Consider replacing it with an emergency/microwave sensor unit. The electrician who has recently tested and modified the installation at HC has been approached and will complete connections on 24 th Nov. Whilst he is there we will seek advice on electrical capacity to meet future needs such as heating. |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | Contractor |
| <i>Progress?</i> | |

| | |
|---------------------------|--|
| <i>Location: Entrance</i> | |
| E02 Notice Board |  |
| <i>Description:</i> | Board needs replacing and text updating. |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | Inhouse |
| <i>Progress?</i> | Elaine Godfrey investigating |

2026 Holy Cross Church Building Quinquennial Review

| | |
|----------------------------------|---|
| <i>Location: Church Building</i> | |
| E03 Fire safety | |
| <i>Description:</i> | Provide No Smoking signs; provide carbon monoxide alarm; test alarm system; review emergency lighting |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | Inhouse |
| <i>Progress?</i> | |

| | |
|----------------------------------|--|
| <i>Location: Church Building</i> | |
| E04 Asbestos remediation | |
| <i>Description:</i> | <p>Work to be undertaken by contractor on 9 December 2025</p> <p>Preparatory work necessary:</p> <p>Clear understairs cupboard - The cupboard under the stairs in the entrance lobby of Holy Cross must be cleared in preparation for remedial work to encapsulate asbestos. Over the years it has become a dumping ground for unused tables and chairs.</p> <p>Clear loft - The loft above the upper room must be cleared in preparation for remedial work to encapsulate asbestos. Again, it has been used as a store for unwanted and unused furniture.</p> <p>Consider insulating loft after work completed.</p> |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | Inhouse |
| <i>Progress?</i> | Job completed December 2025 |

| | |
|------------------------|--------------------------------------|
| <i>Location: Lobby</i> | |
| L01 Lobby | |
| <i>Description:</i> | Seal joint between screen and lintel |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | Inhouse |

2026 Holy Cross Church Building Quinquennial Review

| | |
|------------------|--|
| Progress? | |
|------------------|--|

| | |
|-------------------------------|--|
| Location: Lobby | |
| L02 Emergency lighting | |
| Description: | <p>Emergency lighting above the door in the lobby is not working, it might be a bulb failure. Whilst the roof was being repaired the power to the lighting circuits was turned off and we effectively performed the annual battery test; they should power the lights for a minimum of 3 hours. The new emergency lights in the church and hall were okay, the older ones did not last the full 3 hours.</p> <p>Health & Safety testing records are needed to record tests. We have contacted Ian Yarrow, H&S at the diocese for copies of these but he has directed us to the online safety toolkit saying we need to record tests there. This seems at odds with the need to provide visiting officials such as the fire safety assessor with logs of these tests on demand.</p> |
| Urgency: | Short term (2026-7) |
| Possible cost? | Inhouse/contractor |
| Progress? | |

| | | |
|-------------------------------|---|---------|
| Location: Lobby/stairs |  | |
| L03 Stairs | | |
| Description | Replace coverings; provide nosings to stairs to meet Disability Act | |
| Urgency: | Short term (2026-7) | |
| Possible cost? | | Inhouse |
| Progress? | | |

2026 Holy Cross Church Building Quinquennial Review

| | |
|-------------------------|---|
| <i>Location: Church</i> |  |
| C01 Church walls | |

| | | |
|-----------------------|---|------------|
| <i>Description:</i> | Damp identified see Cotswold Treatments recommendations | |
| <i>Urgency:</i> | Medium term (2028-9) | |
| <i>Possible cost?</i> | | Contractor |
| <i>Progress?</i> | | |

| | |
|-------------------------|---|
| <i>Location: Church</i> |  |
| C02 Sacristy | |
| <i>Description:</i> | Damp recorded. decorate |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | |
| <i>Progress?</i> | |

| | |
|-------------------------|---|
| <i>Location: Church</i> | |
| C03 Plant Room | |
| <i>Description:</i> | Provide fine stopping to hole at high level |
| <i>Urgency:</i> | Short term (2026-7) |

2026 Holy Cross Church Building Quinquennial Review

| | | |
|----------------|--|---------|
| Possible cost? | | Inhouse |
| Progress? | | |

| | |
|--|---|
| <i>Location: Church building</i> | |
| C04 Church & Upper Room heating | |
| <i>Description:</i> | Heaters & timers - Provide reliable timers able to handle switching fan heaters of 2.5Kw to warm the church for Thursday and Saturday masses. Review heating to determine best option(s) |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | |
| <i>Progress?</i> | |

| | |
|----------------------------------|---|
| <i>Location: Church Building</i> | |
| C05 Fire safety | |
| <i>Description:</i> | Provide No Smoking signs; provide carbon monoxide alarm; test alarm system; review emergency lighting |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | |
| <i>Progress?</i> | |

2026 Holy Cross Church Building Quinquennial Review

| | |
|--|--|
| Location: Upper Room U01 Upper Room floor |  |
|--|--|

| | |
|-----------------------|--|
| Description: | Flooring needs review & possible lifting & replacing |
| Urgency: | Short term (2026-7) |
| Possible cost? | Contractor |
| Progress? | |

| | |
|---|--|
| Location: Upper Room U02 Upper floor toilets | |
| Description: | Toilets need refurbishment |
| Urgency: | Short term (2026-7) |
| Possible cost? | Inhouse |
| Progress? | <p>A blocked toilet in the female WC prompted the removal of one of the toilets and because of the poor state of the under floor it was not replaced.</p> <p>The internal partitioning was removed and an indicator lock added to the door.</p> <p>Both the male and female WCs are now unisex with the door signs reflecting this.</p> <p>Include in the review U01 and decorate.</p> |

2026 Holy Cross Church Building Quinquennial Review

| | |
|-----------------------------|---|
| Location: Upper Room | |
| U03 Chair lift | |
| Description: | Installation of chair lift for disabled access to upper room |
| Urgency: | Medium term (2026-7) |
| Possible cost? | |
| Progress? | Explore possibility of installing a chair lift when flooring repaired in Upper Room |

| | |
|--|-----------------------------|
| Location: E1 | |
| External - Front & side elevation window frames | |
| Description: | Need cleaning and painting |
| Urgency: | medium term (2028-9) |
| Possible cost? | Inhouse |
| Progress? | |

| | |
|----------------------------------|--|
| Location: E2 | |
| External – entrance doors | |

2026 Holy Cross Church Building Quinquennial Review

| | | |
|-----------------------|--|--|
| <i>Description:</i> | Glazed door needs decorating; gutters need cleaning; damaged stone on flank wall needs attention | |
| <i>Urgency:</i> | medium term (2028-9) | |
| <i>Possible cost?</i> | Inhouse | |
| <i>Progress?</i> | <p>Gutters twice yearly routine maintenance job</p> <p>Following the discovery of a long term leak the roof above the entrance lobby has been repaired and the fascia and soffit replaced.</p> | |

| | | |
|-----------------------|---|--|
| <i>Location: E3</i> |  | |
| Roof | | |
| <i>Description:</i> | Moss needs removing | |
| <i>Urgency:</i> | medium term (2028-9) | |
| <i>Possible cost?</i> | Inhouse | |
| <i>Progress?</i> | Twice yearly routine maintenance job | |

| | | |
|----------------------------------|--|--|
| <i>Location: E4</i> | | |
| External – rear elevation | | |
| <i>Description:</i> | Fascia needs decorating; ivy needs removing; defective rendering should be made good | |
| <i>Urgency:</i> | medium term (2028-9) | |
| <i>Possible cost?</i> | Inhouse | |

2026 Holy Cross Church Building Quinquennial Review

| | |
|-----------|---|
| Progress? |  |
|-----------|---|

| | |
|-----------------------------------|--|
| Location: E5 | |
| External: side elevation to steps | |
| Description: | Seal joint at change of thickness; remove vegetation |
| Urgency: | medium term (2028-9) |
| Possible cost? | Inhouse |
| Progress? | |

| | |
|-------------------------------------|---|
| Location: E6 | |
| External – side elevation flat roof | |
| Description: | Flat roof needs stripping & recovering |
| Urgency: | Short term (2026-7) |
| Possible cost? | Inhouse |
| Progress? | Resurfaced by JD Home Improvements 2024 |

| | |
|------------------------------------|---|
| Location: E7 | |
| External – side elevation to house | |
| Description: | Wall – localised repointing 10 sqm; high level buttresses rendering needs repairing; repair approx. 450mm of coping to flat roof; |

2026 Holy Cross Church Building Quinquennial Review

| | |
|-----------------------|--|
| | escape door fill cracks to lintel |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | Inhouse |
| <i>Progress?</i> | Buttress cleaned and repaired 2024 Fr George |

| | |
|---|---|
| <i>Location:</i> E8 External side elevation escape stairs | |
| <i>Description:</i> | Considered unsafe; adapt or extend hand rail |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | Inhouse |
| <i>Progress?</i> | Gate in place to restrict access. This is no longer escape route. Signage has been removed. |

| | |
|--|---|
| <i>Location:</i> E9 External side elevation overhead cable | |
| <i>Description:</i> | Remove cable |
| <i>Urgency:</i> | Short term (2026-7) |
| <i>Possible cost?</i> | Inhouse |
| <i>Progress?</i> | Was TV cable from presbytery loft space |